	Type Hits Search Text			DBs
	Туре	nits) Search lext	
1	BRS	0	oxidize same (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	46	oxidize with fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	1660	(cu "cu" copper) with fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	10	(oxidize with fuse) and ((cu "cu" copper) with fuse)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
5	BRS	2	oxidized same (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
6	BRS	0	6375159.URPN.	USPAT
7	BRS	17 .	("4647340" "4826785" "4985750" "5321264" "5321322" "5420455" "5523253" "5608257" "5663590" "5731624" "5760674" "5795819" "6061264" "6078091" "6111301" "6163062" "6175145").PN.	USPAT
8	BRS	3	6111301.URPN.	USPAT
9	BRS	2	6111301.URPN.	USPAT
10	BRS	4	oxidation same (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	2	oxidizing same (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	3	oxidizing adj ambient and (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	0	oxidizing adj ambient same (cu "cu" copper) adj fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
14	BRS	66	(("cu" copper) with fus\$4 and oxid\$7 with copper and (438/\$257/\$)) (("cu" copper) with fus\$4 and oxid\$7 with fuse and (438/\$257/\$))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	9	fus\$3 near (cu copper "cu") and (copper cu "cu") near oxid\$6 and (438/\$6 257/\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp ▽	Comments	Error Definition	Errors
1	2002/06/04 14:52			0
2	2002/06/04 14:52	-		0
3	2002/06/04 14:52			0
4	2002/06/04 14:52			0
5	2002/06/04 14:51			0
6	2002/06/04 14:48			0
7	2002/06/04 14:48			0
8	2002/06/04 14:45			0
9	2002/06/04 14:44			0
10	2002/06/04 14:37			0
11	2002/06/04 14:37			0
12	2002/06/04 14:35			0
13	2002/06/04 14:34			0
14	2002/06/04 14:27			0
15	2002/06/04 14:06			0

	Туре	Hits	Search Text	DBs
16	BRS	3	fus\$3 near2 (cu copper "cu") near2 oxid\$6 and (438/\$6 257/\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	1	(fus\$3 near (cu copper "cu") and (copper cu "cu") near oxid\$6 and (438/\$6 257/\$6)) not (fus\$3 near (cu copper "cu") same oxid\$6 and (438/\$6 257/\$6))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	11	fus\$3 near (cu copper "cu") same oxid\$6 and (438/\$6 257/\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	0	fus\$3 near (cu copper "cu") same OXID\$6(OXIDN-DISC) and (438/\$(438/539.5) 257/\$(257/712-717))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	64	<pre>fus\$3 near (cu copper "cu") same oxid\$6</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	0	30 and (438/\$ 257/\$)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	38	fus\$3 near (cu copper "cu") with oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	3.8	fus\$3 near (cu copper "cu") with oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	20	fus\$3 with (cu copper "cu") and (cu copper "cu") near oxid\$6 and (438/\$6 257/\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	6	(fus\$3 with (cu copper "cu") and (cu copper "cu") near oxid\$6 and (438/\$6 257/\$6)) not ((fus\$3 with (cu copper "cu") same (cu copper "cu") near oxid\$6) and (438/\$6 257/\$6))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	378	fus\$3 with (cu copper "cu") and (cu copper "cu") near oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	14	(fus\$3 with (cu copper "cu") same (cu copper "cu") near oxid\$6) and (438/\$6 257/\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	1	fus\$3 with (cu copper "cu") and program\$5 with oxid\$6 not (fus\$3 with (cu copper "cu") and program\$4 with oxid\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	10 .	fus\$3 with (cu copper "cu") and program\$4 with oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

[Time Stamp ▽	Comments	Error	Errors
	Time Stamp	Commencs	Definition	EITOIS
16	2002/06/04 14:05			0
17	2002/06/04 13:45			0
18	2002/06/04 13:32	•		0 .
19	2002/06/04 13:20			0
20	2002/06/04 13:14			0
21	2002/06/04 13:02			0
22	2002/06/04 12:01			0
23	2002/06/04 12:00			0
24	2002/06/04 11:58		·	0
25	2002/06/04 11:58			0
26	2002/06/04 11:47			0
27	2002/06/04 11:45			0
28	2002/06/04 11:02			0
29	2002/06/04 10:58			0

	Туре	Hits	Search Text	DBs
30	BRS	220	(fus\$3 with (cu copper "cu") same (cu copper "cu") near oxid\$6) not (((fus\$3 with (cu copper "cu") with oxid\$6) and (438/\$ 257/\$)) (fus\$3 with (cu copper "cu") and program\$4 with oxid\$6))	EPO; JPO;
31	BRS	39	fus\$3 with (cu copper "cu") and blow\$4 with oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
32	BRS	231	fus\$3 with (cu copper "cu") same (cu copper "cu") near oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	565	fus\$3 with (cu copper "cu") with oxid\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	33	(fus\$3 near (cu copper "cu") with oxid\$6) not ((fus\$3 with (cu copper "cu") with oxid\$6) and (438/\$ 257/\$))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	28	(fus\$3 with (cu copper "cu") with oxid\$6) and (438/\$ 257/\$)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	169		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	2	(fus\$3 with (cu copper "cu") adj oxid\$6 and (fus\$3 with (cu copper "cu") near oxid\$6 and (fus\$3 with (cu copper "cu") with oxid\$6))) and ((257/529).CCLS.)	USPAT
38	IS&R	452	(257/529).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
39	IS&R	476	(257/529).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	201	fus\$3 with (cu copper "cu") near oxid\$6 and (fus\$3 with (cu copper "cu") with oxid\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
41	BRS	0	fus\$3 with (cu copper "cu") with oxid\$6 with program\$4 and (fus\$3 with (cu copper "cu") with oxid\$6)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

		1	Frre	
	Time Stamp ♥	Comments	Error Definition	Errors
30	2002/06/04 10:43			0 .
31	2002/06/04			0 .
32	2002/06/04 10:37			0
33	2002/06/04 10:14	-		0
34	2002/06/04 10:10			0
35	2002/06/04 10:03			0
36	2002/06/04 09:49			0
37	2002/06/04 09:46			0
38	2002/06/04 09:45		·	0
39	2002/06/04 09:45			0
40	2002/06/04 09:37			0
41	2002/06/04 09:33			0